362 WISCONSIN

```
CREEN RAY
     NEW RICHMOND RGNL (RNH)(KRNH)
                                             2 N UTC-6(-5DT) N45°08.87′ W92°32.35′
                                                                                                           H-2J, L-14I, A
        aaa
              B NOTAM FILE RNH
                                                                                                                   ΙΔΡ
        RWY 14-32: H5507X75 (ASPH) S-30, D-60 MIRL
          RWY 14: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Tree.
          RWY 32: REIL. PAPI(P4L)-GA 3.0° TCH 20'. Tree.
        RWY 04-22: 2050X75 (TURF)
                                    0.3% up NE
          RWY 22: Trees.
        SERVICE: S4 FUEL 100LL, JET A, UL94 0X 4 LGT MIRL Rwy 14-32 preset on low inst: to increase ints and ACTIVATE
          PAPI and REIL Rwys 14 and 32—CTAF. Rwy 32 PAPI unusable byd 4° right of course.
        AIRPORT REMARKS: Attended continuously. 24 hr self fuel avbl for credit card users or call 715-246-5338. Seaplane tfc
          adjacent to south side of arpt. Deer and birds on and invof arpt. Aerobatic practice area 4NM northeast of arpt. Ultralight
          activity on and invof arpt. Turbo-jet touch and go not authorized. Bright Igts from ball fields 1/2 mile south during evenings
          May thru Sep. Rwy 04-22 marked with white cones. Open to ski equipped acft winter months. Rwy distance markers on
          Rwy 14. Automobile and pedestrian access onto arpt property restricted by security fencing and gates from
          0400-1200Z‡. Contact arpt manager 715-246-7735 for access instructions.
        AIRPORT MANAGER: 715-246-7735
        WEATHER DATA SOURCES: AWOS-3 120.0 (715) 246-3202.
        COMMUNICATIONS: CTAF/UNICOM 122.975
       ® MINNEAPOLIS APP/DEP CON 121.2
          GCO 121.725 (MINNEAPOLIS APCH CTL AND FLIGHT SERVICES)
        RADIO AIDS TO NAVIGATION: NOTAM FILE PNM.
          GOPHER (H) VORTACW 117.3 GEP Chan 120 N45°08.74' W93°22.39' 084° 35.4 NM to fld. 877/6E. HIWAS.
     NORTH COUNTRY SPB (See SOLON SPRINGS on page 374)
OCONTO
     OCONTO-J DOUGLAS BAKE MUNI (OCQ)(KOCQ) 2 SW UTC-6(-5DT) N44°52.44′ W87°54.59′
                                                                                                             CREEN RAY
               B NOTAM FILE GRB
                                                                                                                 I -31A
                                                                                                                   ΙΔΡ
        RWY 11-29: H3198X75 (ASPH) S-40, D-55, 2D-90 MIRL
          RWY 11: REIL. PAPI(P2L)-GA 4.0° TCH 31'. Trees.
          RWY 29: REIL. PAPI(P2L)-GA 4.0° TCH 31'. Trees.
        RWY 04-22: 1840X150 (TURF)
          RWY 04: Trees
          RWY 22: Trees.
        SERVICE: FUEL 100LL LGT ACTIVATE MIRL Rwy 11-29-122.8. Rwy 29 PAPI unusbl byd 8° rgt of cntrln.
        AIRPORT REMARKS: Attended Mon-Fri irregularly. 24 hour fuel avbl. Migratory waterfowl on and invof arpt. Confirm winter rwy
          conditions and snow removal with arpt manager 920-834-7727. Rwy 04-22 not plowed Nov-Apr. Rwy 04-22 thlds
          marked with white cones
        AIRPORT MANAGER: 920-834-7727
        WEATHER DATA SOURCES: AWOS-3 120.925 (920) 835-1599.
        COMMUNICATIONS: CTAF/UNICOM 122.8
       R GREEN BAY APP/DEP CON 120.3 (1130-0530Z‡ other times ctc)
       ® MINNEAPOLIS APP/DEP CON 125.55
        RADIO AIDS TO NAVIGATION: NOTAM FILE GRB
          GREEN BAY (H) VORTACW 115.5 GRB Chan 102 N44°33.31′ W88°11.69′ 031° 22.7 NM to fld. 767/1E.
              2AWIH
          VOR unusable:
            270°-300° blo 7,000′
           ______
     SWEETWATER BAY SPB (3ØW) 6 NE UTC-6(-5DT) N44°57.12′ W87°48.51′
                                                                                                             GREEN BAY
              NOTAM FILE GRR
        WATERWAY ALL-WAY: 10000X250 (WATER)
        SEAPLANE REMARKS: Attended irregularly. Apch from the W or NW over western shoreline; trees up to 85' along shoreline.
        AIRPORT MANAGER: (920) 634-8201
        COMMUNICATIONS: CTAF 122.9
```