

**INDIANAPOLIS DOWNTOWN HELIPORT** (8A4) 0 N UTC-5(-4DT) N39°45.95' W86°08.93'

ST LOUIS

732 B NOTAM FILE HUF

L-27D

HELIPAD H1: H60X60 (CONC)

IAF

HELIPAD H1: NSTD.

**SERVICE:** S2 FUEL JET A1+ LGT ACTIVATE ODALS; NSTD PLASI; and High Ints Pad Lgts—CTAF. ODALS westbound ingress. Helipad H1 NSTD PLASI—Pulsating apch slope indicator—on east apch.

**HELIPORT REMARKS:** Attended Mon-Fri 1300-2130Z, Sat-Sun on req. For attendant and information call 317-955-1271. For weekend assistance 317-487-5089. Fuel self serve. Minor repairs available on req call 317-487-5089. All tfc remain south of heliport; utilize railroad tracks and interstate highways for ingress/egress. Apch and departure on easterly or westerly headings. Helipad H1 building area to northeast is lgtd. Heliport has noise abatement procedures contact heliport manager 317-955-1271.

**AIRPORT MANAGER:** (317) 487-5022**WEATHER DATA SOURCES:** AWOS-3 118.250 (317) 955-3160.**COMMUNICATIONS:** CTAF/UNICOM 123.05

Ⓡ APP/DEP CON 125.275

**CLEARANCE DELIVERY PHONE:** For CD etc Indianapolis Apch at 317-227-5743.**RADIO AIDS TO NAVIGATION:** NOTAM FILE HUF.**SHELBYVILLE (L) VOR/DME** 112.0 SHB Chan 57 N39°37.95' W85°49.46' 297° 17.0 NM to fld. 805/1E.

VOR unusable:

Byd 25 NM blo 3,000'

180°-270° byd 17 NM blo 6,000'

**COMM/NAV/WEATHER REMARKS:** Ingress/egress coordination with IND Apch is encouraged—125.275.**INDIANAPOLIS EXECUTIVE** (TYQ)(KTYQ) 14 NW UTC-5(-4DT) N40°01.84' W86°15.09'

CHICAGO

922 B NOTAM FILE HUF

H-5E, 10F, L-27D

**RWY 18-36:** H5500X100 (CONC-GRVD) S-45, D-90 HIRL

IAF

**RWY 18:** REIL. PAPI(P2L)—GA 3.0° TCH 51'. Hangar.**RWY 36:** REIL. PAPI(P2L)—GA 3.0° TCH 53'. Tree.

**SERVICE:** S4 FUEL 100LL, JET A, A+ OX 1, 2, 3 LGT HIRL Rwy 18-36 preset on med ints dusk to dawn; to incr ints and ACTIVATE REIL Rwy 18 & Rwy 36—CTAF. PAPI Rwy 18-36 operates continuously.

**AIRPORT REMARKS:** Attended 1100-0100Z. For svcs after hrs call FBO on 317-769-4487. Self svc 100LL fuel avbl 24 hrs with credit card. For fuel and acft svcs ctc FBO on 130.4. Conditions not monitored 0100-1100Z. Remote controlled model acft activity 0.1 NM west of Rwy 18-36, surface—400' AGL. Rwy 36 calm wind/crosswind rwy.

**AIRPORT MANAGER:** (317) 385-3015**WEATHER DATA SOURCES:** AWOS-3PT 120.725 (317) 769-3154.**COMMUNICATIONS:** CTAF/UNICOM 123.05

Ⓡ INDIANAPOLIS APP/DEP CON 127.15 (Active Rwy 14-32 at IND) 124.65 (Active Rwy 05-23 at IND)

**GCO** 121.725 (INDIANAPOLIS CLNC and FLIGHT SERVICES, 4 slow clicks to activate) (If unavbl call 317-227-5743)**RADIO AIDS TO NAVIGATION:** NOTAM FILE HUF.**BRICKYARD (H) VORTACW** 116.3 VHP Chan 110 N39°48.88' W86°22.05' 021° 14.0 NM to fld. 872/1E.

TACAN unusable:

312°-346° byd 25 NM blo 4,000'

**ILS** 111.3 I-TYQ Rwy 36. Autopilot coupled approach na below 1,900' MSL.**COMM/NAV/WEATHER REMARKS:** APP/DEP CON sectorization based on active rwy at Indianapolis International arpt.