TWIN CITIFS

FLYING CLOUD (FCM)(KFCM) 11 SW UTC-6(-5DT) N44°49.65' W93°27.52' 906 B NOTAM FILE FCM H-2J. L-12J. 14H. A RWY 10R-28L: H5000X100 (ASPH-GRVD) S-30, D-60 HIRL IAP, AD RWY 10R: MALSR, PAPI(P4L)-GA 3.0° TCH 42', Tree, Rgt tfc, ŝ RWY 28L: REIL. PAPI(P4L)-GA 3.0° TCH 44'. Tree. RWY 10L-28R: H3898X75 (ASPH) S-30, D-60 MIRL Residentia 4 Area *4*3 RWY 10L: REIL, PAPI(P4L)-GA 3.0° TCH 39'. RWY 28R: REIL. PAPI(P4L)-GA 3.0° TCH 38'. Rgt tfc. C RWY 18-36: H2690X75 (ASPH) S-12.5 MIRL 03 Baseba RWY 18: REIL, PAPI(P4L)-GA 3.5° TCH 45', Tank. G Field 03 \mathcal{C} RWY 36: REIL. PAPI(P4L)-GA 3.0° TCH 27'. Fence. Ă5 SERVICE: S4 FUEL 100LL, JET A 0X 3, 4 LGT When twr clsd ACTIVATE and incr ints HIRL Rwys 10R-28L, MIRL Rwy 18-36 and 9 Rwy 10L-28R, MALSR Rwy 10R, PAPI Rwy 18, Rwy 36, Rwy 10L, Rwy 28R, Rwy 10R, Rwy 28L, REIL Rwy 18, Rwy 36, Rwy 28L, Rwy Residential Area 10L, Rwy 28R-CTAF. Rwy 36 PAPI unusable byd 6° left of cntrln. AIRPORT REMARKS: Attended continuously. Self serve fuel avbl 24 hrs with credit card. JET A ldg fee, ctc FBO. Rwy 10L-28R CLOSED when twr G 0 $\hat{\alpha}$ clsd. Arpt CLOSED to jets not meeting FAR 36, jet training and acft with $\hat{\alpha}$ n certificated MGTOW higher than 60,000 lbs. Maintenance run-ups are prohibited between 0400-1300Z[‡]. Ultralight ops prohibited. Deer, 62 ß birds, and wildlife on and invof arpt. When twr clsd, snow removal operators monitor 119.15. For noise abatement procedures, www.macnoise.com/pilots. Acft please follow voluntary noise abatement procedures. Rwy 10R is calm wind rwy when twr clsd. Twy A between Premier Jet Ramp and Thunderbird Ramp clsd to acft wingspans 56' or greater. Twy A clsd east of Baron Lane to acft with wingspans 54' or greater. Twy D clsd from Twy D2 to apch end Rwy 36 to acft with wingspans of 66' or greater. Twy D btn D1 and D2 clsd to acft with wingpans 48' or greater. Rwy incursion risk - pilots are reminded to review arpt Hot Spot info bfr txg for dep & bfr ldg. See TPP Arpt Diagram & Chart Suppl sxn on Hot Spots for addn info. Wrong rwy arr risk, closely aligned parl rwys. See TPP Arpt Diagram. Ldg fee. AIRPORT MANAGER: (952) 944-1035 WEATHER DATA SOURCES: ASOS 124.9 (952) 941-4156. COMMUNICATIONS: CTAF 119.15 ATIS 124.9 UNICOM 122.95 **R** MINNEAPOLIS APP/DEP CON 134.7

TOWER 119.15 125.2 (1200-0300Z‡, 1st Sun in Nov-2nd Sat in Mar; 1200-0400Z‡, 2nd Sun in Mar-1st Sat in Nov.)

AIRSPACE: CLASS D svc 1200-0300Z‡ 1st Sun in Nov-2nd Sat in Mar, 1200-0400Z‡ 2nd Sun in Mar-1st Sat in Nov; other

ILS 109.7 I-FCM Rwy 10R. Class IT. Glideslope unusable byd 5° right of course. Unmonitored when twr clsd.

(L) VORW/DME 117.7 FCM Chan 124 N44°49.52' W93°26.56' at fld. 900/1E.

MINNEAPOLIS CLNC DEL 121.7 (When twr closed)

RADIO AIDS TO NAVIGATION: NOTAM FILE FCM.

GND CON 121 7

times CLASS F.,

VOR/DMF unusable: 290°-305° blo 4.000'

184